

HAMM TANDEMWALZE HD 8 VV

?????? ???? ?		BILDER
?? ?	16987	     
?? ?	2012	
???? ?	521	
???? [??]	1,58	
???? ?	✓	
???? ? ?	✓	
???? ? ? ? ? ? ? ?	✓	
???? ? ? ? ? ?		
????	Kubota	
?? ?	D1005-ET05	
?? ? ? ? ? ? ? ? ?	14,8	
?? ? ? ? ? ? ? ?	Tier4/EPA2011	
???? ? ? ? ? ? (?????)	✓	

?????			
?????	?????	???????	???
?? ?	✓		
?????	✓		
???? ?	✓		
???? ?	✓		
?????	✓		
?????	✓		
?????	✓		
?????	✓		
?????	✓		
?????	✓		
?????	✓	Schelle zwischen Krümmer und Flexrohr undicht	
?????	✓		
???? ?	✓		

????????	??????	????????	???
??????	✓		
?????	✓		
????????	✓		
????????	✓		
????????	✓		
?????? ?????	✓		
??????/????	??????	????????	???
????????	✓		
??????	✓		
?????? ?????	✓		
????????	??????	????????	???
????????	▲	Abblendlicht VL ohne Funktion	
???? ?????	✓		
????????	✓		
????????	▲	Batteriepole korrodiert, Batteriespannung: 8V	
?????? ?????	✓		
????????	??????	????????	???
????????	50%		
?? ?????	70%		
????	60%	11	
????	??????	????????	???
?????/????	✓		
???? ?????	✓		
?????	✓		
?????	✓		