



DYNAPAC KETTENFERTIGER F 141 C

???????		BILDER
??? ??????	17010	 
??? ??????	2003	 
????? ????????	9500	 
????? [??]	17,5	 
???????		
???????	Cummins	
??? ?????? ????????	129	
????? ?????? (???????)	✓	
???????????		
?????? - ????????	VB 851 TV	
????? / ????	✓	
?????? ???	✓	
[?] ??? ????????	2,5 - 5	
???????	2x 62cm 2x 25cm+ Materialleitbleche	
????? ??????? ??	✓	
????? ??????? - ??????? [????]	2	
????? ?????????? ????????	✓	
????? ????????	✓	

???????			
???????	???????	???????	???
??? ???????	✓		
?????????	✗	3 Ventildeckeldichtungen schwitzen, Kraftstoffschlauch feucht	
???? ?????	✓		
????? ????????	✓		
???????	✓		
?????????	✓		
?????????	✓		
????????? ????????	✓		
???????????	???????	???????	???
???????	✗	Gummimantel abgerieben	
???????	✗	Schwitzt an Schlauchflansch	
???????????	✓		
???????????	✗	Telekopzyylinder Bohle ein-/ausfahren schwitzen leicht	
???????????	✓		
????????? ????????	✓		
??????/???????	???????	???????	???
???????	✗	Beide Sitzpolster gerissen	
???????	✗	Display schlecht lesbar, Pixelfehler	
??????? ????????	✓		
???????????	???????	???????	???
???????	▲	Hinten o.F., vorne fehlt	
????? ????????	✓		
???????????	✓		
???????????	✓		
????????? ????????	✓		

???????	??????	???????	???
?????	40%		
????? ?????	80%		
????? ????????	80%		
????? ????????	20%		
???????	??????	???????	???
?????? - ????	50%		
?? ?????? ??????	70%		
????	70%	2 Schneckenflügel gebrochen	
????	??????	???????	???
??????/???	✓		
??????/?????	✓		
???? ????????	✓		
?????	✗	Seitenhaube links leicht verbogen, Halter f. Beleuchtung und Niv.-Skala fehlt	
?????	✓		
?????	✓		