



WIRTGEN BODENFRÄSEN/-RECYCLER WR 2400

??????? ???? ?		BILDER
??? ?????	17045	     
??? ?????	2007	
????? ???????	8943	
????? [??]	25,6	
???? ?????????	✓	
????? ??? ??????	✓	
?????? ???????		
??????	Mercedes	
??? ??????	OM 502 LA AG3	
??? ?????? ??????? ???	420	
??????????		
??? ?????? [??]	2400	
??? ?????? [??]	500	
????? ??????	✓	
????? ??????	✓	

??????			
??????	✓	??????	???
??? ??????	✓		
???????	✓		
????? ??????	✓		
????? ???????	✓		
???????	✓		
???????	✓		
???????	✓		
?????? ???????	✓		

????????	??????	????????	???
??????	✓		
?????	✓		
????????	✓		
???????	✓	Trommelhubzylinder Links schwitzt	
????????	✓		
?????? ?????	✓		
??????/????	??????	????????	???
????????	✓		
??????/??????	✓	Heckscheibe gerissen	
??????	✓	Zündschlüssel Schlüssel abgebrochen	
????????	✓		
?????? ?????	✓		
????????	??????	????????	???
????????	✓		
???? ?????	✓		
????????	✓		
????????	✓		
?????? ?????	✓		
????????	??????	????????	???
?????? ????? ????	70%		
?????? ????? ????	70%		
?????? ????? ????	60%		
?????? ????? ????	60%		

???????	??????	???????	???
????? ?????	60%	Wurde rechte und linke Seitenwand im Verschleißbereich erneuert	     
????? ????? (???)	70%	Mehrere Meißel abgebrochen	
???????	70%		
????	??????	???????	
??????/???	✓		
?????/?????	✓		
???? ????????	✓		
?????	✓	an einigen Stellen geschweißt	
?????	✓		
????	✓		